



State of Utah

Department of
Natural Resources

ROBERT L. MORGAN
Executive Director

Division of
Oil, Gas & Mining

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

August 3, 2004

TO: Minerals File

FROM: Paul Baker, Senior Reclamation Biologist *PBB*

SUBJECT: Site Inspection, Deloy Shumway, Travertine #8 and 9, S/019/053, Grand County, Utah

Date of Inspection: May 10, 2004
Time of Inspection: About 6:00 to 6:30 p.m.
Conditions: Mostly cloudy, 80's
Participants: Paul Baker, DOGM

Purpose of Inspection:

I had not seen the site in nearly one and one-half years and wanted to see if some of the trash had been cleaned up and if there had been any other activity.

Observations:

While there is still quite a lot of trash lying around, it is not as bad as in December 2002 (compare Photos 1 and 2 and 3 and 4). The trailer in Photo 1 is now at the bottom of the hill next to the fenced area (Photo 7). Otherwise, there has been very little change in site conditions.

Conclusions and Recommendations:

The Division and the BLM should continue to monitor this site and ensure trash does not accumulate. Some additional work could be done to clean up the trash, but it is not too bad. Otherwise, I know of no particular concerns.

PBB:jb

cc: Deloy Shumway
Moab BLM

O:\M019-Grand\S0190053-Travertine\inspections\ins-05102004.doc

**ATTACHMENT
Photographs**

S/019/053, Travertine #8 and 9, Deloy Shumway

Inspection Dated: May 10, 2004; Report Dated: August 3, 2004



Photo 1. Overview of part of the area at the top of the hill in December 2002.



Photo 2. 2004 picture of the same area as in Photo 1.



Photo 3.



Photo 4.



Photo 5. This area is uphill from the area shown in Photos 1 and 2.



Photo 6.



Photo 7. Looking down the hill to the fenced storage area. Note the trailer in the upper left.